



FIG. 3.6 Burn-down lip machined into a circular plate to increase welded-joint reliability.