



FIG. 10.28 Illustration of strain distribution introduced into a conductor from bending. Tensile strain occurs along the outside of the bend, compressive strain along the inside, and zero strain along the neutral axis. (From Ekin 1981a.)