



FIG. 3.15 Cut-away view of indium O-ring cryogenic vacuum compression seal. The O-ring is formed by wrapping pure indium wire around the stainless-steel ring; the ring is then placed in the apparatus and squashed by bolting together the two stainless-steel pieces labeled SS and SS'.