



FIG. 3.5 Example of choosing materials that will tighten a joint on cooling. The brass screw contracts more than the copper heat-sink post, increasing the pressure holding the post against the sample holder.