



FIG. 3.8 Design joints so they have large soldered-surface areas for mechanical strength, especially with joints subjected to bending stress and soldered with low-melting temperature (less than about 100 °C) bismuth-based alloys.