



FIG. 4.18 Helium-gas trap for venting a dewar without allowing air to condense and freeze in the dewar or vapor-cooled leads.