



FIG. 8.10 Diagram of contact resistance measurement, showing extra voltage leads attached to each current pad close to a current lead. The potential difference between the extra voltage lead and a voltage tap placed anywhere on the superconductor can be used to monitor the voltage across the pad/superconductor interface.