



FIG. 3.18 Degassing rate for *untreated* metals, compared with Neoprene<sup>™</sup> plastic and Araldite<sup>™</sup> epoxy (from Blears et al. 1960).