



FIG. 4.13 Removable vacuum lead-through for continuous leads. The lip of epoxy provides a good vacuum seal and also prevents the tube from being sucked through the vacuum coupling; the epoxy lip can be conveniently made by using the technique shown below in Fig. 4.14.